
# **ALTERNATIVE 3 - Two Travel Lanes, Center Turn Lane, and Buffered Bike Lanes**




### Description

- One through lane in each direction
- •Center left turn lane space may also be used as a median or a pedestrian refuge island
- •Enhance signal operations to mitigate traffic impacts
- Upgrade and install new crosswalks, where feasible
- Buffered bike lanes possible



## Intersection Delay and Level of Service Grade

		EXISTING	ALTERNATIVE 3	
Intersection	Time of Day	Delay (sec)	Delay (sec)	Change (sec)
N Howard St & Seminary Rd	AM	36.8	34.5	-2.3
	PM	21.4	25.9	+4.5
St. Stephens Rd & Seminary Rd	AM	11.7	16.5	+4.8
	PM	8.1	10.9	+2.8
N Quaker Ln & Seminary Rd	AM	69.1	61.1	-8.0
	PM	53.2	42.5	-10.7



#### Scoring

- Concepts were scored on a scale of 1 to 5 for each of the objectives for the project.
- One point is given for concepts that make no improvements or substantially worsen existing conditions.
- Five points are given for concepts that substantially improve conditions or fully preserve existing strengths of Seminary Road.

PERFORMANCE MEASURE	RATING
PEDESTRIAN SAFETY/COMFORT	
FILLING THE SIDEWALK GAP	
CONTROLLING SPEED	
PREVENTING CRASHES	
MINIMIZING VEHICLE DELAY	
ADJACENT RESIDENT LIVABILITY	
BICYCLIST SAFETY/COMFORT	

#### **Performance Assessment**

- Ped Safety/Comfort: Provides the most comfort and safety for people walking. Upgraded crosswalks, signage/marking, and median islands make for safe, visible, convenient, and comfortable access and mobility for people walking.
- Filling the sidewalk gap: Allows space to fill the sidewalk gap in partnership with VTS.
- Controlling Speed: Reduced, narrowed lanes calm traffic, do not allow passing, and reduce speeding.
- Preventing car crashes: Reduced and narrowed lanes provide the best crash reduction benefits, likely to reduce angle, sideswipe, or rear-end crashes the most of all alternatives.

## **Performance Details**

- Minimizing vehicle delay: Changes in intersection delay are generally minimal and improve in some cases. The worst average delay is seen at Howard Street with an additional <u>5 seconds</u> of wait time in the evening peak period. Left turns are eased with a dedicated turn lane.
- Adjacent resident livability: Provides dedicated turn lane for left turning vehicles. Ample space for cars to pull out of driveways. or side streets with increased sight distances.
- Bicycling Safety/Comfort: Provides the best facility of the alternatives with a buffered bicycle lane on each side of the roadway.